

13/12  
2023

**DELHI JAL BOARD; GOVERNMENT OF N.C.T. OF DELHI**  
**OFFICE OF THE EXECUTIVE ENGINEER (D-014)**  
**E BLOCK PARK: PREET VIHAR: DELHI-110092**

Phone No. 20825101, Mail ID: - [djb.aeem62@gmail.com](mailto:djb.aeem62@gmail.com)

No. DJB/F.2/EE (D-014)/2025-26/ 02

DATED: 17/4/25

To,  
 DM (East),  
 LM Bundh, Shastri Nagar,  
 Delhi-110031

**Subject:- Regarding action taken report on illegal bore wells uploaded on DJB portal.**

A Joint survey was carried out with concerned ZRO Staff and with staff of DM East regarding tracing and sealing of 31 Nos of illegal bore wells. The status has already been provided by the concerned ZRO to the area SDM. However, the status is again submitted as below:-

S.No	S.No as per uploaded list	Add/Name of the property	No. of bore wells	Status/remarks
1	117	H.N 4 RAGHUBAR PURA	01	Does not pertain to District East
2	118	PARIVAR APARTMENT IP EXT PHARGANJ	01	Disconnected & Sealed by SDM Staff
3	119	C BLOCK G.N 6 GAJIPUR	01	Address is not traceable
4	120	11/226 KALYAN PURI	01	Disconnected & Sealed by SDM Staff
5	121	D OR C BLOCK G.N 2 GAZI PUR DARIY FARM	01	Could not be identified due to incomplete / improper address
6	122	H.N 203 G,N 4 NEAR GUPTA LAXMI NAGR	01	Could not be identified due to incomplete / improper address
7	123	H.N 4 RAGHUBAR PURA	01	Does not pertain to District East
8	124	C BLOCK G.N 6 GAJIPUR	01	Could not be identified due to incomplete / improper address
9	125	E -90 K SAMNE NEW ASHOK NAGAR	01	Disconnected & Sealed by SDM Staff
10	126	FRONT OF BANSAL CHANDAN NAGAR	01	Could not be identified due to incomplete / improper address
11	127	B-138 / 5 LAXMI NAGAR	01	Could not be identified due to incomplete / improper address
12	128	C-342 G.N 5 NEW ASHOK NAGAR	01	Disconnected & Sealed by SDM Staff
13	129	C-148 PANDAV NAGAR RADHA KRISH	01	Disconnected & Sealed by SDM Staff

	130	8/249 TRILOK PURI	01	No bore well exist
	131	H.N 1 PRIYADARSHNI VIHAR	01	Disconnected & Sealed by SDM Staff
16	132	D BLOK DARIY FARM GAZIPUR DELHI	01	Could not be identified due to incomplete / improper address
17	133	C-II/45B C-II/110A BLOCK NEW ASHOK NGR	01	Disconnected & Sealed by SDM Staff
18	134	WEST GURU ANGAD NAGAR	01	Could not be identified due to incomplete / improper address
19	135	WEST GURU ANGAD NAGAR	01	Could not be identified due to incomplete / improper address
20	136	WEST GURU ANGAD NAGAR	01	Could not be identified due to incomplete / improper address
21	137	H.N 80 WEST GURU ANGAD NAGAR	01	Disconnected & Sealed by SDM Staff
22	138	R-199B G.N 10 RAMESH PARK	01	Disconnected & Sealed by SDM Staff
23	139	H.N 7/5277 G.N 7 KRISHNA NAGAR I	01	Could not be identified due to incomplete / improper address
24	140	H.NO 8/42 TRILOK PURI	01	Disconnected & Sealed by SDM Staff
25	141	G.N 3 SHAKARPUR PILER NO	01	Could not be identified due to incomplete / improper address
26	142	RZN 90 G.N 1 VIJAY ENC	01	Could not be identified due to incomplete / improper address
27	143	A BLOCK RAGHUNATH MANDIR A BLOCK	01	Could not be identified due to incomplete / improper address
28	144	H.N 79 SUNDER PARK SHASTRI NAGAR	01	Disconnected & Sealed by SDM Staff
29	145	NEW ASHOK NAGAR A BLOK 669	01	Could not be identified due to incomplete / improper address
30	146	11 A GANESH NAGAR EXT SHAKAR PUR	01	Disconnected & Sealed by SDM Staff
31	147	B-31 KRISHNA COMPLEX	01	Could not be identified due to incomplete / improper address

Executive Engineer (East-1 & II)